QUALITY CONTROL

Name of the Work:	Drilling of 4 no's of Borewell & fixing of pump motor and necessary accessories at Abbigere & Chikkasandra in different locations, in ward no.12, in Shettyhalli Sub Division.
Job No:	012-14-000037
Work order No:	BBMP/DZ/EE/DD/WO/93/2014-15, Date:27.06.2014.
BR No:	534/14-15, Date:30.08.2014.

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 01 years back.

Assistant Executive Engineer
Shettyhalli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike